Upper Santa Ana Valley Groundwater Basin, Yucaipa Subbasin

Groundwater Basin Number: 8-2.07

• County: San Bernardino

• Surface Area: 25,300 acres (39 square miles)

Basin Boundaries and Hydrology

The Yucaipa Subbasin underlies the southeast part of San Bernardino Valley. It is bounded on the north by the San Andreas fault, on the west by the Redlands fault and the Crafton Hills, on the south by the Banning fault, and on the east by the Yucaipa Hills. The average annual precipitation ranges from 12 to 28 inches. This part of the San Bernardino Valley is drained by Oak Glen, Wilson, and Yucaipa Creeks south and west into San Timoteo Wash, a tributary to the Santa Ana River.

Hydrogeologic Information

Water Bearing Formations

Groundwater is found chiefly in alluvium, with lesser quantities in the San Timoteo Formation and fractured bedrock beneath the alluvium (Moreland 1970). Specific yield is estimated to vary from less than 4 percent northeast of Yucaipa, to a maximum of about 10 per cent in the southeastern part of the subbasin (DPW 1934). Alternatively, specific yield is estimated to range from about 6 to 22 percent (DWR 1967a), with the average for the subbasin of about 10 percent (DWR 1979).

Alluvium. Alluvial deposits in the subbasin are divided into older and younger units. The Holocene age younger alluvium consists of unconsolidated boulders, gravel, sand, silt, and clay (Moreland 1970). This unit forms a thin veneer and is mostly above the water table (Moreland 1970). The middle to late Pleistocene age older alluvium consists of boulders, gravel, sand, silt, and clay (Moreland 1970), and holds the primary source of groundwater in the subbasin. Clays present in this section are due to weathering and soil formation during accumulation of the deposits (DPW 1934).

San Timoteo Formation. The Pliocene-Pleistocene age San Timoteo Formation consists of alluvial deposits that have been folded and eroded. These deposits are widely distributed and principally composed of gravel, silt, and clay, with comparatively small amounts of calcite-cemented conglomerate. The clasts are chiefly granitic, with lesser amounts of volcanic and metamorphic pebbles and cobbles (DPW 1934). The total thickness of the San Timoteo Formation is estimated to be between 1,500 and 2,000 feet, but logs of deep wells near the central part of the subbasin indicate water-bearing gravels to depths of only 700 to 1,000 feet (DPW 1934).

Restrictive Structures

Several structures disrupt groundwater flow in the subbasin (DWR 1967a; Todd 1988; Wildermuth 2000). The Chicken Hill fault, Yucaipa barrier,

Casa Blanca barrier, and Gateway barrier all restrict groundwater movement, trend northeasterly, and were formed in response to differential movements along the San Andreas and Banning faults (Todd 1988). These structures displace water levels as much as 160 feet across them (Moreland 1970). The Oak Glen fault and the South Mesa barrier trend northwesterly and are the result of sympathetic movement related to the San Andreas and Banning faults (Todd 1988). These structures displace water levels as much as 120 feet across them (Moreland 1970). The Redlands (Wildermuth 2000) and Crafton faults have displacements of groundwater levels (DWR 1967a), which indicate that they are partial barriers to groundwater flow. In the western part of the subbasin, northeast-dipping beds of the San Timoteo Formation form barriers that cause groundwater to rise to the surface (DWR 1967a).

Recharge Areas

Dominant recharge to the subbasin is from percolation of precipitation and infiltration within the channels of overlying streams, particularly Yucaipa and Oak Glen Creeks, underflow from the fractures within the surrounding bedrock beneath the subbasin, and artificial recharge at spreading grounds. Four artificial recharge facilities were noted in 1967 (DWR 1967b) with a total capacity of about 56,500 af/yr. By increasing the spreading acreage along Oak Glen Creek by 25-50 acres, the capability exists to spread 7,000 to 14,000 af of surface water annually to recharge the Yucaipa Subbasin (YVWD 2000a).

Groundwater Level Trends

Water level records in most parts of the subbasin show relatively small seasonal fluctuations and a steady decline from 1918 through 1933, without significant recovery during the following wet years (DPW 1934). Increased pumping and reduced recharge caused by below-normal precipitation resulted in an increased rate of water level decline of 10 to 20 feet per year beginning in 1945 (Moreland 1970). This rate of decline continued into the early 1960s then was reduced to 5 to 10 feet per year in 1969 (Moreland 1970).

The water table in the Yucaipa Subbasin slopes steeply from the San Andreas fault through a narrow gap to Yucaipa, then flattens southwest of Yucaipa. At Liveoak Creek and other ravines in the north, the water table reaches the surface. Fluctuations in water levels were usually around 5 to 10 feet annually (DWR 1934). The subbasin currently is in an overdraft state; however, water levels are at or near historic highs. Groundwater within the subbasin is typically reached between 200 to 280 feet below the surface (YVWD 2000a).

Groundwater flow is generally from areas of recharge in the north and east along the edges the San Bernardino Mountains and the Crafton and Yucaipa Hills, towards the Bunker Hill Subbasin on the southwest and west (Wildermuth 2000; YVWCD 2000a).

Groundwater Storage

Groundwater Storage Capacinty. The total capacity of the subbasin has been estimated to be 807,517 af (YVWD 2000), 783,000 af (DWR 1986), and 1,230,000 af (DWR 1967a). The estimated storage capacity of the upper 100-foot zone in the Yucaipa Subbasin is 99,000 af (DPW 1934).

Groundwater in Storage. Groundwater in storage in 1986 was estimated to have been about 585,700 af (Mann 1986) and in 1960 to be about 626,000 af (DWR 1967a).

Groundwater Budget (Type A)

Inflow into the subbasin from natural recharge for 1988 is estimated to have been 7,900 af and subsurface inflow is considered negligible (Todd 1988). Artificial recharge is through spreading of surface water, but accounts for less than 1,000 af (YVWD 2000a). Groundwater extractions for domestic and irrigation use is 13,800 af/yr (YVWD 2000a). Subsurface outflow is 890 af/yr (Todd 1988). Using these figures, the total change in storage for the subbasin in 1988 would be a loss of about 5,790 af. The amount of groundwater extracted in 1980 was estimated to be 4,485 af and the estimated deep percolation for 1980 through 2040 ranges from 14,900 to 20,300 af (DWR 1986).

Groundwater Quality

Characterization. Groundwater in the subbasin is calcium-sodium bicarbonate in character (DWR 1966; SBVWCD 2000). Water sampled from 43 public supply wells show an average TDS content of approximately 322 mg/L with a range of 200 to 630 mg/L. The average TDS content has also been estimated to be 343 mg/L (DWR 1986) and 334 mg/L (SBVWCD 2000).

Impairments. Nine wells sampled north and west of Yucaipa showed high sulfate and nitrate levels (DPW 1933), although in the 1960s no wells showed significant nitrate concentrations and only one well was slightly elevated with sulfate content (DWR 1966).

Water Quality in Public Supply Wells

•		
Constituent Group ¹	Number of wells sampled ²	Number of wells with a concentration above an MCL ³
Inorganics – Primary	43	1
Radiological	44	1
Nitrates	46	12
Pesticides	43	4
VOCs and SVOCs	44	1
Inorganics – Secondary	43	4

¹ A description of each member in the constituent groups and a generalized discussion of the relevance of these groups are included in *California's Groundwater – Bulletin 118* by DWR (2003).

Bulletin 118 by DWR (2003).
 Represents distinct number of wells sampled as required under DHS Title 22 program from 1994 through 2000.

Well Characteristics

Well yields (gal/min)				
Municipal/Irrigation	Range: 2 – 2,800 gal/min Total depths (ft)	Average: 206 gal/min		
Domestic	Range: 18 – 1,070 ft	Average: 302 ft		
Municipal/Irrigation	Range: 150 – 1,150 ft	Average: 497 ft		

Active Monitoring Data

Agency	Parameter	Number of wells /measurement frequency
USGS	Groundwater levels	19
USGS	Miscellaneous water quality	3
Department of Health Services and cooperators	Title 22 water quality	45

Basin Management

Groundwater management: Water agencies	The YVWD is currently involved with development of a groundwater management plan (AB3030 plan) to prescribe collective management of the subbasin (YVWD 2000a).
Public	Yucaipa Valley Water District
Private	

References Cited

- California Department of Public Works, Division of Water Resources (DPW). 1933. South Coastal Basin Investigation: Quality of Irrigation Waters. Bulletin No. 40. 95 p.
- _____. 1934. South Coastal Basin Investigation: Geology and Ground Water Storage Capacity of Valley Fill. Bulletin No. 45. 279 p.
- California Department of Water Resources (DWR). 1966. Mineral Quality of Ground Water in the Bunker Hill-San Timoteo Area. Southern District Technical Information Record Study Code No. 335-5-A-8. 10 p.
- ______. 1967a. Specific Yield and Storage Determination for the Bunker Hill-San Timoteo Ground Water Investigation. Southern District Technical Information Record Study Code No. 1335-5-A11. 15 p.
- ______. 1967b. Fresh Water Artificial Recharge in the Bunker Hill-San Timoteo Area. Southern District Technical Information Record Study Code No. 1335-5-B-8.
- ______. 1979. Preliminary Evaluation of State Water Project Ground Water Storage Program: Bunker Hill – San Timoteo – Yucaipa Basins. Southern District Technical Information Record Study Code No. 1610-6-J-1. 82 p.

³ Each well reported with a concentration above an MCL was confirmed with a second detection above an MCL. This information is intended as an indicator of the types of activities that cause contamination in a given basin. It represents the water quality at the sample location. It does not indicate the water quality delivered to the consumer. More detailed drinking water quality information can be obtained from the local water purveyor and its annual Consumer Confidence Report.

- _____. 1986. San Bernardino-San Gorgonio Water Resources Management Investigation. Southern District. 83 p.
- Fox, Robert C. 1990. *Groundwater Resources Monitoring Plan.* Consultant's report prepared for the Yucaipa Valley Water District. Yucaipa California. 136 p.
- Mann, John F. 1986. *Revised Safe Yield of the Yucaipa Basin*. Consultant's report prepared for the Yucaipa Valley Water District. Yucaipa, California.
- Moreland, Joe A. 1970. *Artificial Recharge Yucaipa, California*. US Geological Survey Open File Report. 44 p.
- Todd, David K., Consulting Engineers Inc. 1988. *Perennial Yield of the Yucaipa Groundwater Basin*. Consultant's report prepared for the Yucaipa Valley Water District. Yucaipa, California. 71 p.
- Wildermuth Environmental, Inc. (Wildermuth). 2000. TIN/TDS Study Phase 2A of the Santa Ana Watershed; Final Technical Memorandum. San Clemente, California, July 2000.
- Yucaipa Valley Water District (YVWD). 2000a. *Urban Water Management Plan and Water Shortage Contingency Plan*. Yucaipa, California.
- _____. 2000b. Water Facilities of the Yucaipa Valley. http://www.yvwd.dst.ca.us. May 2002.

Additional References

- Burnham, W. L. and L. C. Dutcher. 1960. Geology and Ground-Water Hydrology of the Redlands-Beaumont Area, California, With Special Reference to Ground-Water Outflow. US Geological Survey Open-File Report. 352 p.
- California Department of Water Resources (DWR). 1960. Upper Santa Ana River Drainage Area Land and Water Use Survey, 1957. Bulletin No. 71. 51 p.
- ______. 1965. Lines of Equal Elevation on the Effective Base of the Ground Water Reservoir Bunker Hill-San Timoteo Area. Southern District Technical Information Record Study Code No. 335-5-A-3. 12 p.
- ______. 1965. Hydrograph Analysis of the Bunker Hill-San Timoteo Area. Southern District Technical Information Record Study Code No. 335-5-A-4. 14 p.
- ______. 1966. Upper Santa Ana River Drainage Area Land and Water Use Survey, 1964. Bulletin No. 71-64. 76 p.
- ______. 1967. Selection of a Base Period for the Bunker Hill-San Timoteo Area. Southern District Technical Information Record Study Code No. 1335-5-B-1.
- _____. 1967. Surface Water Inflow-Outflow for the Bunker Hill-San Timoteo Area. Southern District Technical Information Record Study Code No. 1335-5-B-2.
- ______. 1967. Components of Flow in Warm Creek. Southern District Technical Information Record Study Code No. 1335-5-B-3.
- ______. 1967. Determination of Seasonal Amounts of Precipitation on the Bunker Hill-San Timoteo Area. Southern District Technical Information Record Study Code No. 1335-5-B-4.
- ______. 1967. Historical Population in the Bunker Hill-San Timoteo Area. Southern District Technical Information Record Study Code No. 1335-5-B-5.
- ______. 1967. Waste Water in the Bunker Hill-San Timoteo Area. Southern District Technical Information Record Study Code No. 1335-5-B-6.
- ______. 1967. Diversion of Streamflow in the Bunker Hill-San Timoteo Area. Southern District Technical Information Record Study Code No. 1335-5-B-7.
- ______. 1969. Consumptive Use in the Bunker Hill-San Timoteo Area.. Southern District Technical Information Record Study Code No. 1335-5-B-10.
- ______. 1969. Deep Percolation Criteria for the Bunker Hill-San Timoteo Area.. Southern District Technical Information Record Study Code No. 1335-5-B-15.

- _______. 1969. Development of Future Inflow and Outflow for the Bunker Hill-San
 Timoteo Ground Water Basin. Southern District Technical Information Record Study
 Code No. 1335-5-C-1.

 ______. 1969. Alternative Plans of Operation for the Bunker Hill-San Timoteo Ground
 Water Basin. Southern District Technical Information Record Study Code No. 1335-5C-3.

 _____. 1970. Meeting Water Demands in the Bunker Hill San Timoteo Area. Bulletin
 104-5.

 _____. 1976. Waste Water in the Bunker Hill-San Timoteo Area. Southern District
 Technical Information Record Study Code No. 1335-5-B-6a.

 _____. 1978. Updated Hydrological Conditions in the Bunker Hill-San Timoteo Area.
 Southern District Letter Report. 91 p.
- Caouette, Norm. 1978. Artificial Recharge in the Bunker Hill-San Timoteo Area 1959-1977. San Bernardino Valley Municipal Water District. 56 p.
- Dutcher, L. C. 1965. Progress Report on Water Studies in the San Timoteo-Smiley Heights Area, Upper Santa Ana Valley, California, 1964. US Geological Survey Open File Report. 31 p.
- Dutcher, L. C. and F. W. Fenzel. 1972. Ground-Water Outflow, San Timoteo-Smiley Heights Area Upper Santa Ana Valley, Southern California, 1927 Through 1968. US Geological Survey Open File Report. 30 p.
- Eccles, Lawrence A. 1979. Ground-Water Quality in the Upper Santa Ana River Basin, Southern California. US Geological Survey Water Resources Investigations 79-113. 51 p.
- Lofgren, Ben E. 1971. Estimated Subsidence in the Chino-Riverside and Bunker Hill-Yucaipa Areas in Southern California for a Postulated Water-Level Lowering, 1965-2015. US Geological Survey Open File Report. 20 p.
- Miller, R. E. and John A Singer. 1971. Subsidence in the Bunker Hill-San Timoteo Area Southern California. US Geological Survey Open File Report. 28 p.
- Moreland, Joe A. 1972. Artificial Recharge in the Upper Santa Ana Valley Southern California. US Geological Survey Open File Report. 51p.

Errata

Substantive changes made to the basin description will be noted here.