

**APPLICATION EVALUATION FORM**  
**2014 Water-Energy Grant Program**  
**FY 2014-2015**

**APPLICANT** El Camino Irrigation District

**GRANT AMOUNT** \$2,435,869  
**REQUESTED**

**PROPOSAL** El Camino Restoration Project  
**TITLE**

**TOTAL PROPOSAL** \$2,435,869  
**COST**

**PROPOSAL DESCRIPTION**

The proposal contains two projects. Project 1 would replace approximately 12,214 ft. of the well 5 system with new 12 inch schedule 80 PVC pipe, hubgates and valves in order to eliminate water loss. Project 2 would replace approximately 8,250 ft. of the well 5 system with new 12 inch schedule 80 PVC pipe, hubgates and valves in order to eliminate water loss.

**PROPOSAL SCORE CRITERIA**

	<b>Energy Savings (kWh/\$Million)</b>	<b>Water Savings (MG/\$Million)</b>	<b>DAC</b>	<b>Agreement Component</b>	<b>Funding Priority</b>
<b>Rank</b>	Low	Low	Yes	Insufficient	-
<b>Original Value</b>	765,940	1,393.364			
<b>Adjusted Value</b>	0	0			

**TECHNICAL REVIEW SUMMARY**

<b>Subject</b>	<b>Attachment</b>	<b>Application Review Comments</b>
Calculation Review	Attachment 2	Unable to verify calculations due to lack of supporting documentation. As a result, the water and energy values have been reduced to "0".
Agreement Components	Attachments 3, 4, and 5	All necessary agreement component requirements were not met, as outlined in the PSP. The Schedule is not consistent with the tasks in the Work Plan; and does not show the timing and duration of the tasks. All Budget estimates are not justified as to their use and magnitude.
DAC Benefit/Status	Attachment 7	Concur with the disadvantaged community (DAC) benefit and status and proposal demonstrates DAC requirements, as outlined in the PSP.